BASEEFA Requirements

The *Delta F Oxygen Cell* is BASEEFA-approved for use in intrinsically-safe installations, when connected to a BASEEFA-approved MIS 1, MIS 2, or MMS 3 hygrometer. BASEEFA-approved MIS 1, MIS2, and MMS 3 hygrometers have serial numbers of 2001 and above.

Follow the instructions in the hygrometer *User's Manual* to properly set up, connect, operate, and maintain the Delta F Oxygen Cell.

!WARNING!
If you connect the Delta F Oxygen Cell to a hygrometer that is not BASEEFA-certified, the oxygen cell certification is invalid.

BASEEFA Certification Numbers

The applicable BASEEFA certification numbers are:

- **MIS 1, MIS 2, MIS 3:** BAS01ATEX7097
- **Delta F Oxygen Cell:** BAS01ATEX1098X

IMPORTANT: *The apparatus is to be installed such that the apparatus terminals are protected to at least the requirements of IP20.*

USA: GE Sensing, 1100 Technology Park Drive, Billerica, MA 01821-4111, USA
Ireland: Sensing House, Shannon Free Zone East, Shannon, County Clare, Ireland

916-043G
June 2007